

## Simple List Poles – Corner Cutout

You can use this template to cut a curved corner off of the legs of your list poles.

Print and cut along the outer edges, then fold along the dotted lines to form flaps.

Place over one end of the 2x6, fold down the flaps, and trace along the curved edge with a pencil.

